

General Environmental Incident Summary

Incident: 4050 **Date/Time Notice:** 3/25/2016 1645 **DEM Incident No:**

Responsible Party: Oliver County Wind

Date Incident: 3/25/2016 **Time Incident:** 1245 **Duration:**

County: Oliver **Twp:** 142 **Rng:** 83 **Sec:** 5 **Qtr:**

Lat: 47.15126 **Long:** -101.22590 **Method:** Interpolation from map

Location Description: Oliver County Wind, 1851 33rd ave sw Center ND 58530. Turbine #4.

Submitted By: Chase Dauenhauer

Affiliation:

Address: 1851 33rd ave SW

City: Center

State: ND

Zip: 58530

Received By:

Contact Person: Chase Dauenhauer
1851 33rd Ave SW Center ND 58530
Center, ND 58530

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Transformer Failure

Description of Released Contaminant: Non-PCB Mineral Oil

Volume Spilled: 30.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Failed Padmount Transformer which caused the oil release

Risk Evaluation:

Non PCB mineral oil came in contact with the soil around the failed padmount transformer. No health hazards to report.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Minimal impact to surface soils best estimate at this time is a 15-20 foot diameter area which will require clean up.

Action Taken or Planned:

Spill was contained using New Pig Spill Response and Containment kit which consists of Pig Pillows and Pig Socks. Pig pillows were used to absorb oil around the padmount transformer and the pig socks were used to eliminate the chance of the oil spreading across the ground.

Wastes Disposal Location: Will contact Clean Harbors for Clean Up and Disposal

Agencies Involved:

Updates

Date: 3/25/2016 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Harries, Alison

Updated Volume:

Notes:

According to the incident summary, this spill involves mineral oil from a transformer. Forward to Division of Waste Management - Hazardous Waste Program.